



GARY R. HERBERT
Governor
SPENCER J. COX
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES


MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

Minerals Inspection Report

Report Date: **09/08/2014**


Reviewed 

Mine Name: La Sal #2	Permit Number: S/037/0125	Mine Status: Inactive
Operator Name: Laramide La Sal, Inc.	Inspection Date: 08/26/2014	Permit Fees: Paid
Inspector(s): M. Bradley	Inspection Time: 2:30pm	Bond Amount: \$69,323
Attendee(s): Doug Rowles, BLM	Weather: Cloudy, warm	Bond Escalation: 08/23/2017
Inspection Purpose: Routine inspection		Prior Inspection: 07/24/2013

Conclusions and Recommendations

Location: 652182.00 m E, 4232399.00 m N, UTM Zone 12N. Inspection was to follow up on operator statement that knapweed occurrence found in 2013 had been addressed. We looked around the location where knapweed was found and saw no evidence of any occurrence on site. Eradication effort appears to have been successful.

Elements of Inspection	Evaluated & Commented	Enforcement
1. <i>Permits, Revisions, Transfer, Bonds</i>	<input type="checkbox"/>	<input type="checkbox"/>
2. <i>Public Safety (shafts, adits, trash, signs, highwalls)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No safety issues present.		
3. <i>Protection of Drainages/Erosion Control</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
No erosion issues present.		
4. <i>Deleterious Material</i>	<input type="checkbox"/>	<input type="checkbox"/>
5. <i>Roads (maintenance, surfacing, dust control, safety)</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Road into site inside the locked gate is covered with Russian thistle.		
6. <i>Reclamation</i>	<input type="checkbox"/>	<input type="checkbox"/>
7. <i>Backfilling/Grading (trenches, pits, roads, highwalls, shafts)</i>	<input type="checkbox"/>	<input type="checkbox"/>
8. <i>Soils</i>	<input type="checkbox"/>	<input type="checkbox"/>
9. <i>Revegetation</i>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
Checked for presence of knapweed after operator stated they had been removed/eradicated. Inspection confirmed no knapweed currently present.		
10. <i>Other</i>	<input type="checkbox"/>	<input type="checkbox"/>

Inspector's Signature: 

CC: Lee "Pat" Gochnour, Laramide La Sal Inc., The Exchange Tower, 130 King St. West, Ste 3680, Toronto, Ontario, Canada M56 181
Doug Rowles, BLM (drowles@blm.gov)

File: /nrwogmfs1/OGM/GROUPS/MINERALS/WP/M037-SanJuan/S0370125-La Sal Mine/inspections/INSP-08262014.pdf





Area immediately west of topsoil stockpile where knapweed was located. No evidence of knapweed now.



Road into site covered with Russian thistle, except where this harvester ant colony has cleared the vegetation away from around the nest entrance.